

DR-8F45AT & DR-16F45AT

FW Release Note Ver. 1.0.1

Date: 2017.06.29

Official FW

(8ch) 53210.1.101406.32

(16ch) 53310.1.101406.32

- Fixed Rebooting issue

Date: 2017.06.16

Official FW (DO NOT USE – Reported rebooting)

(8ch) 53210.1.101404.32

(16ch) 53310.1.101404.32

- Fixed Rebooting issue during Aging (Record Audit occurred)
- Fixed the problem that video is not displayed when Playback Pause Zoom (BPM - 2644)
- Support TVI 720p 50 fps / TVI 720p 60 fps (Implemented to record 60 fps at 30 fps)
- 3MP TVI camera COAXITRON support
- [WEBRA] Fixed a problem not saving the schedule setting (Motion recording) (SALESQNA - 2227)
- [WEBRA] Corrected a problem that does not appear on Live 1 split screen when connected with Schnell 3 MP TVI camera (1920 x 1536 resolution) (SALESQNA - 2228)
- [WEBRA] Fixed When it turned out ENHANCED PASSWORD, Password of 9 characters or more could be input (fixed to limit 8 characters only)
- [WEBRA] Mail - Fixed Check box of snapshot not synchronized (problem of automatically released the check box)

Date: 2017.04.21

Official FW (DO NOT USE – Reported rebooting)

(8ch) 53210.1.101305.32

(16ch) 53310.1.101305.32

- Enhanced security rule applied
- Double authentication feature added
- (Bug) When IP Camera does not support Second Stream of 640 x 360, exception handling will be operated so as not to display black video on 16 split PlayBack screen and Thumbnail.
- Fixed screenshot save bug
- Fixed Backup Player bug
- Fixed displaying Blank in lower side when connecting to SD
- Reboot problem when using capital letters while creating Login ID (Problems according to User authority)

Date: 2017.04.14

Official FW 101104

(8ch) 53210.1.101104.32

(16ch) 53310.1.101104.32

- Enabled IP camera search and add
- Fixed embedded backup player issue.
- Onvif PTZ bug fixed
- AXIS M3007 model 2nd stream play bug fixed

Date: 2016.8.17

Passed Version: 10029

(8ch) 53210.1.100029.32

(16ch) 53310.1.100029.32

1. HTTPS support for PCI compliancy issue